

GOODYEAR S.A. RECALL

GOODYEAR TREADMAX 295/80R22.5 154/149M UltraGrip Coach HL (2 Tyres)
GOODYEAR NEXT TREAD 315/80R22.5 156/150K MSDII (1 Tyre)



- GOODYEAR TREADMAX 295/80R22.5 154/149M UltraGrip Coach HL tyres manufactured during
- week 03 of 2026 and identification number G52 8914435256 (1 tyre)
- week 11 of 2026 and identification number G52 8916633353 (1 tyre)
- GOODYEAR NEXTREAD 315/80R22.5 315/80R22.5 156/150K MSDII tyres manufactured during
- week 04 of 2026 and identification number G52 8913418446 (1 tyre)

HAZARD

- Those retread tire references were produced under nonconforming cure conditions. This nonconformity may result in incomplete vulcanization of the tread or bonding surface and lead to tread separation in service which could increase the risk of accident.
- This program is part of the company's commitment to product quality and safety.

WHAT TO DO

- If you have an affected tyre, please contact a Goodyear dealer to arrange an inspection and a replacement of any affected tyres free of charge.

REMEDY

- Replacement of any affected tyres free of charge

CONTACT

- Please contact a Goodyear dealer
- Or send Email to goodyear_eprel_customer_support@goodyear.eu