

GOODYEAR S.A. RECALLS GOODYEAR EAGLE F1 SUPERSPORT 255/35ZR20 (97Y) & 305/30ZR21 (104Y)



- 255/35ZR20 (97Y) Goodyear Eagle F1 SUPERSPORT XL tyres manufactured during weeks 22 of 2024 and 36, 37 of 2025
They can be identified by a DOT tyre identification number on the sidewall of the tire reading 1DM5V JACR 2224 , 1DM5V JACR 3625, 1DM5V JACR 3725
- 305/30ZR21 (104Y) Goodyear Eagle F1 SUPERSPORT XL tyres manufactured during weeks 23 of 2024 and 35, 36, 37 of 2025
They can be identified by a DOT tyre identification number on the sidewall of the tire reading 1DMKX JD1R 2324, 1DMKX JD1R 3525, 1DMKX JD1R 3625, 1DMKX JD1R 3725

HAZARD

- Those references do not comply with regulatory high-speed requirements. This nonconformity may lead to tread deformation or a crown separation when running at high speed, possibly leading to a loss of control of the vehicle and increase the risk of injury.
- There are no reports of any accidents, loss of control or of any damage or injury related to the recall tyres but this program is part of the company's commitment to product quality and safety.

WHAT TO DO

- If you have an affected tyre, please contact a Goodyear dealer to arrange an inspection and a replacement of any affected tyres free of charge.

REMEDY

- Replacement of any affected tyres free of charge

CONTACT

- Please contact a Goodyear dealer
- Or send Email to goodyear_eprel_customer_support@goodyear.eu